



Group summary statistics

xbar Chart for Poly Etch Rate




Process Capability Analysis for Poly Etch Rate




Group summary statistics

R Chart for Poly Etch Rate




Normal Q-Q Plot



Poly_Etch_Rate

Run chart



Capability plot

